



■ F-900 Calibration Chart

Calibration	C ₂ H ₄ ppm sensor	C ₂ H ₄ ppb sensor	CO ₂ PCT sensor	CO ₂ ppm sensor	O ₂ sensor
Set Zero	Daily	Daily	6 months	Weekly	6 months
Set Span	6 months	Weekly	6 months	6 months	6 months