



■ F-950 Calibration Chart

Calibration	C ₂ H ₄ ppm sensor	CO ₂ PCT sensor	O ₂ sensor
Set Zero	Daily	6 months	6 months
Set Span	6 months	6 months	6 months